Tesco Corporation **Technical Bulletin** 5616 - 80th Avenue SE Calgary, Alberta, Canada T2C 4N5 No: TB085 Rev: 0 Date: 29 July 2011 Tel: 1-877-TESCO-77 (North America) Tel: 1 (713) 359-7195 (AMSS 24-hour support) Tel: 1 (713) 359-7295 (International) Improper Build Procedures Email: bulletins@tescocorp.com Found on 37C "A" Cables www.tescocorp.com TESCO www.tescoparts.com

BACKGROUND INFORMATION:

TESCO recently encountered two issues with the 37C "A" cable, predicated by improper build procedures by the primary cable vendor.

1. Issue 1: Incorrect Pinning

The supplied cables were pinned incorrectly. The insert that is supplied with the cables has a ground strap attached to Pin 3 as standard vendor issue. The insert requires that the ground strap be removed (Figure 1). However, during the most recent cable assemblies completed at the vendor, the ground strap was not removed from the insert. The result is a short to ground when the circuit involving Pin 3 is energized. It is believed that a number of these improperly built cables made it through TESCO supply chain, and may have been included with your top drive.




Figure 1: Ground strap shown on the insert

2. Issue 2: Use of Wrong Potting Material

Permanent epoxy was used in the back end of the 37C cable end (Figure 2). Using this permanent epoxy essentially makes the cable end irreparable, and upon any issues, the end will need to be cut off and replaced. TESCO's standard assembly for the 37C "A" cable uses a silicon based gel that supplements water-proofing, but does not harden. This allows repairs and pin replacements when required.




Figure 2: Incorrect use of permanent epoxy

AFFECTED PRODUCT:

All TESCO 37C "A" cables with the following TESCO part numbers:

Part Number	Description	
4108	Cord,Ext,Robotics"A",#14,37C,69M	
4109	Cord,Pgtl,Female,Robotics,D2P/D6P,#14,37C,49M	
730841	Cord,Ext,Robotics"A",EMI 400,#14,37C,69M	

ACTION REQUIRED:

To date, 38 cable assembles have been repaired or replaced. It is estimated that an additional 30 cable assemblies require corrective action. All TESCO Business Units should inspect their inventory and report back to whether they have these cables and if they are affected, and notify customers regarding this issue.

TESCO recommends the following procedures to resolve the above two 37C "A" cable issues:

1. Test cables for proper pinning to determine if ground strap has been removed

- a. On a 37C "A" cable, file the outer case of the Pyle National sheet to ensure good contact (Figure 3).
- b. Ensure the finish on the filed end of the cable is removed (Figure 4).
- c. Use a digital voltmeter and set it to "Continuity". Place the leads across Pin 3 and the filed end of the Pyle National outer case (Figure 5). If there is no ringing while the voltmeter is set to "Continuity", this means the grounding strap is removed and the cable is good. If there is continuity (indicating low resistance), then the ground strap is still in the assembly.



Figure 3: Filing the outer case of the Pyle National sheet



Figure 4: Filed end of 37C cable with finish removed



Figure 5: Place a DVM leads across Pin 3 and filed end of cable

2. Replace Cables Using Wrong Potting Material

Check all new 37C "A" cables sent to TESCO Business Units in the last year that have not yet been used. Once informed of the quantity required TESCO will arrange for replacement cables to be sent in exchange for the non-conforming cables, which will be sent back to the vendor for repair. If this arrangement does not prove to be cost effective, alternative arrangements will be made where the local service facility will complete the repair and replacement parts will be sent to accomplish the job.

	Version	Date (D/M/Y)	ECN	Description of Bulletin Changes
Ī	Rev 0	29/07/2011		Initial release of document