

PRODUCT: TOP DRIVE

DATE: April 14, 2011


SUBJECT: Replacement Rotary Manifolds

MODELS: 8050,1050,1250 with 6.81 & 7.12 gear ratio, 1275, 6027

DISCUSSION: In an effort to improve top drive reliability, Canrig has modified the rotary manifold mounting plate on select models. They now have a larger radius where the hydraulic fittings attach to the ports. These new mounting plates can be installed on existing units but require a change in hydraulic fittings and hoses. The old mounting plates have been discontinued.



OLD STYLE



NEW STYLE

RECOMMENDATION:

When ordering a replacement mounting plate, place an order for the mounting plate specified in the parts book. If it is a discontinued part, you will receive the new part with all the hoses and fittings required to install. If it is the new style, you will receive the replacement part as ordered.

When ordering a replacement rotary manifold, place an order for the rotary manifold specified in the parts book. If it is a discontinued assembly, you will receive the new assembly with all the hoses and fittings required to install. If it is the new style, you will receive the replacement part as ordered.

TOP DRIVE MODEL	OLD ROTARY MANIFOLD ASSY	REPLACEMENT ROTARY MANIFOLD ASSY
6027	AY10247	AY17840
8050-1250	AY10133	AY17832
1275	AY10114	AY17084

INFORMATION:

For further information contact:

For a complete list of all bulletins go to www.canrig.com

Canrig Drilling Technology Ltd.

8223 Willow Place Drive South
Houston, Texas 77070
Phone: 281.774.5600
Fax: 281.774.5650

7475 51 Street SE
Calgary, AB T2C 4L6
Phone: 403.237.6400
Fax: 403.536.4605