Technical Bulletin

No: TB066 Rev: 0 Date: 01 Apr 2009

Description: CDS™ HPU Lift Kit and CDS™ HPU



Tesco Corporation 3993 W. Sam Houston Pkwy N. Suite 100 Houston, Texas.77043 Phone: (713) 359-7000 www.tescocorp.com

BACKGROUND INFORMATION:

In response to a request from the Asia Pacific Business Unit (APBU), TESCO Engineering have redesigned the Casing Drive System[™] (CDS) Hydraulic Power Unit (HPU) lift set to comply with the requirements of EN12079, DNV2.7-1 and DNV2.7-3 (offshore container codes).

The HPU lift set and HPU lift point design changes are detailed in ECN-150-0033 and detailed analysis is recorded in Analysis Report 1500052 available upon request.

The following parts or documents were discontinued and replaced with new part/document numbers:

Old Document / Part Number	New Document / Part Number	Description
500345	1500044	Frame, Lifting, Dual Pump, HPU, CDS
500379	1500053	HPU Assembly, Dual Pump, Zone1, 3-Function, CDS
500344	1500054	Kit, Lifting, Dual Pump, HPU, CDS
500380	1500045	Frame, Dual Pump, Zone 1, 46"x75", HPU, CDS
WI-500379	T-1500053	CDS-HPU Start Up and Testing Procedure

AFFECTED PRODUCT: Casing Drive System™

ACTION REQUIRED: No action required, for information only

Contact your local TESCO Parts and Service Center for further information regarding this bulletin and or supply of affected components noted above.

5/4/2009 1:48 PM Page 1 of 1 Technical Bulletin TB066