

# Change Bulletin

No: CB007

Rev: 0

Date: February 12, 2007

## Description: ECI Mechanical Module Tarp Set




Tesco Corporation  
6204 – 6A Street SE  
Calgary, AB. T2H 2B7  
Phone: (403) 692 5700  
[www.tescocorp.com](http://www.tescocorp.com)

**TESCO**<sup>®</sup>

### BACKGROUND INFORMATION:

The ECI cold climate mechanical module tarp set (PN PK045) has been superseded and is replaced by PN 1130012. This change was made to improve naming consistency and to generate a new illustration showing the installation of the tarps. Figure 1 shows the correct tarp installation. Please refer to illustration I-1130012 for complete specifications. This change is documented fully by ECN 113-0014.



**Figure 1** – Correct tarp set installation

### AFFECTED PRODUCT:

This change is applicable to ECI mechanical modules with the following part numbers 14096, 15098, 15451, 19049.

### ACTION REQUIRED:

When purchasing a tarp set for ECI mechanical modules with part numbers listed above, please order using part number 1130012. Refer to illustration I-1130012 for proper installation.

-----  
**Contact your local TESCO Parts and Service Center for further information regarding this bulletin and or supply of affected components noted above.**