



Technical Bulletin TB-013

From: Tesco Products - Applications

Date: May 16, 2003

MODELS: EC/HC/HS only

Re: Pipe Handler Interlock

There has been an interlock kit developed by Tesco designed to further prevent the pipe handler from rotating if the pipe handler lock is not fully engaged after using the pipe handler feature. The kits have been developed for the EC/HC and HS models, which were not originally equipped with a pipe handler interlock system. This new feature should be used in addition to the inspection procedure as outlined in Tesco Safety Bulletin SB001 and must be installed by qualified personnel.

Please contact Tesco Technical Applications ASAP for assistance in determining the correct configuration for your equipment.

If there are any questions related to this Technical Bulletin please immediately contact

Tesco Products-Applications

(403)-233-0757

[Mike Crocker Applications Group](#)