



PRODUCT: AUTOMATED CATWALKS

DATE: Mar 20, 2008

SUBJECT: TRANSFORMER POLE GUARD


SERIAL NUMBERS: ALL PC2000's, PC3000's, PC4000's, TM80 AND TM120 HPU's

DISCUSSION: Service personnel are exposed to high voltage due to the exposed poles on the control transformer when opening the main PLC panels.


RECOMMENDATION:

Install kit number AY50485 which consists of a (2) guards and nylon acorn nuts to insulate anyone accessing the main PLC panel.

******CAUTION****** When installing the kit ensure power to the PLC panel is disconnected at the MCC.



WITHOUT GUARD INSTALLED



WITH GUARD INSTALLED

To arrange for parts or installation, please contact your field service coordinator.

INFORMATION:



For further information contact:

For a complete list of all bulletins go to www.canrig.com

Field Service
Canrig Drilling Technology Ltd.

14703 FM 1488
Magnolia, Texas 77354
Phone: 281.259.8887
Fax: 281.259.8158

7475 51 Street SE
Calgary, AB T2C 4L6
Phone: 403.237.6400
Fax: 403.233.2667



DRILL $\phi 1/4"$
TYP



CANRIG DRILLING TECHNOLOGY CANADA LIMITED © 2006.
THE DRAWINGS, INFORMATION AND SUBJECT MATTER
HEREOF ARE THE CONFIDENTIAL, SOLE AND EXCLUSIVE
PROPERTY OF CANRIG DRILLING TECHNOLOGY CANADA
LTD. AND ARE NOT TO BE COPIED, REPRODUCED OR USED
IN ANY MANNER FOR ANY PURPOSE WHATSOEVER
WITHOUT WRITTEN CONSENT OR DIRECTION.

KIT, XFMR BOLT PROTECTION
SHEET 1 OF 1
DATE CREATED: 26 February, 2008 11:31:06 AM
PART NO: **AY50485**
REV: **REL-01**

REV.	DESCRIPTION	DATE
REL-01	RFM	2/27/2008

This page intentionally left blank