



CANRIG DRILLING TECHNOLOGY LTD

PRODUCT BULLETIN NUMBER: 62

## SAFETY ALERT

DATE: January 22, 2001

**SUBJECT:** BEARING REMOVAL

**SERIAL NUMBERS:** ALL

**DISCUSSION:** Removing Bearings with hydraulic press (or other mechanical means) could cause the bearing to fail and come apart, creating a hazard or cause injury.

**RECOMMENDATION:** DO NOT REMOVE ANY BEARING WITHOUT PROPER PROCEDURE.

Use proper tooling whenever pressing off bearings. Always follow the manufacturers recommendations. Take proper precautions to safeguard against bearing failure or injury.

If in doubt, contact CANRIG for appropriate procedures before attempting any removal or installation of parts on the CANRIG Top Drive.

**INFORMATION :**

For further information contact:

Field Operations Manager  
Canrig Drilling Technology Ltd.  
14703 FM 1488  
Magnolia, Texas 77354  
Phone: 281.259.8887  
Fax: 281.259.8158

This page intentionally left blank